

Date of Inspection : 24.12.2020		District: W. Champaran.	
Division : RWD, WORK. Div. Bagaha-1		Length (km): 3.90 km. (2.004 km)	
Name of the Road: Sabaya Chauri to Murea via Mahui path. (unframed)			
Scheme/Programme:		MAINTENANCE	
Package No.: RM/WE/BAGH/19/0001		Road Id No.: 31809002020	
Status of the Project:		Ongoing/Completed/Under Maintenance NEW MAINTENANCE	
Work is a case of:		New Connectivity/Up gradation/ Maintenance NEW MAINTENANCE	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	—	S
b)	Condition of Surfacing	—	S
c)	Riding Quality	—	S
d)	Road Camber	—	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		yes
4.	Compliance History		
a)	Status of ATR's & any others		NO

C.C. Pavement -
is not provided.

Overall Rating :

Satisfactory (S)	—	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: Ratnesh Paswan.
DESIGNATION: Executive Engineer

(Signature) 24/12/2020