Date of Inspection: 24.12.2020		District: no. Champaran -
Division: PWP, Wo	rk. Division. Badaha	Length (km):
Name of the Road: B	arma Chandraul	to Parlan
Scheme/Programme:	MAINTENANCE	to far Jayn, Road.
Package No.: RM WE	1	Road Id No.: 31809002016
Status of the Project:	The state of the s	d/Under Maintenance
Work is a case of: New Connectivity/11		

WOLK	12 M CH26 OI:	New Connectivity/Up gradation/ Maintenance New	Maindenand	
Sl. No		Parameters to be checked	Remarks	
1.	Pavement		244000	
a)	Road Junction condition			
b)	Condition of S	S		
c)	Riding Quality	-		
d)	Road Camber	<u>S</u>		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)		ints provided or not (CC Pavement)		
g)		flank/slope & raincuts if any	1000	
2.	Cross Drainag		Jes	
a)	Condition of he	ad walls in Hume pipe culverts including its painting	S	
b)		butment & Wing walls, Slab in RCC culverts	٥	
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furnitur	e	1	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		yes	
	Compliance His	tory		
) 5	Status of ATR's	& any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ratherh Parman.
DESIGNATION: Executive Engineer