Divi Nan	sion: RWD, WOYK. Bir. Bayla re of the Road: Bankatura Po	1 0 1		
Sche	eme/Programme: MAINTENA	ANCE		
Pack	cage No .: RM WE 1844 19 0	00 Road Id No.: 3180900 211	0	
Stati	us of the Project: Ongoing/Con	mpleted/Under Maintenance		
Wor	k is a case of: New Connec	ctivity/Up gradation/ Maintenance New. M	aintenance	
SI. I		Parameters to be checked		
1.	Pavement	Remarks		
a)	Road Junction condition	0		
b)	Condition of Surfacing		S	
c) Riding Quality		2		
d)			2	
, camber			S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		5	
f)		raction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		4.1	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S	
b)	Condition of Abutment & Wi	ng walls, Slab in RCC culverts	S	
c)	Condition of railings/slab/app			
3.	Road Furniture			
)	Whether sign boards/inform stones/Pavement road marking	atory/cautionary Board/km & 200m gs are provided and maintained	yes	
Jeoiron	Compliance History			
	Status of ATR's & any others	_ 40		
-		AND THE RESIDENCE OF THE PROPERTY AND TH	1	

Overall Rating :

Satisfactory (S)	S	
Satisfactory but requires Improvement (SRI)	processor published programme and programme administration and the second	
Unsatisfactory (U)		

(Signature)

NAME: Ratheslack Executive Engineer
DESIGNATION: - Executive Engineer