Date of	Inspection: 24.12.2020	District: 20. Chamba			
Divisio	11: RWD, NOTK- Dir. Baylan	Length (km): 3.630 km.	ran.		
Name o	of the Road: Balua to Baga	hi Sakhuani			
	Programme: MAINTENANCE	29 Knuan			
	Package No.: RM WE BAH 19 000 Road Id No.: 34809007001				
Status of the Project: Ongoing/Completed/Under Maintenance					
Work is	s a case of: New Connectivity/	Jp gradation/ Maintenance			
SI. No.	Parameters to be checked New Connectivity/Up gradution/ Maintenance New Maintenance Parameters to be checked Remarks				
1.	Pavement		Vemstk2		
a)	Road Junction condition				
		S			
b)	Condition of Surfacing	5	1.		
c)	Riding Quality		る		
d)	Road Camber	7	M		
e)	Whether free from defects suc aggregates in case of CC Pavement.	S	C.C. Partement		
f)	Contraction Joints provided or not (CC Pavement)			ن	
g)	Compaction of flank/slope & raincuts if any			C.C. Pa	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridges			-	
3.	Road Furniture				
$\frac{1}{s}$	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		yes		
. C	Compliance History				
St	atus of ATR's & any others	- HO			

Overall Rating

Satisfactory (S)		S
Satisfactory but requi	res Improvement (SRI)	
Unsatisfactory (U)		

(Signature)

NAME: Rathesh Paswar.

DESIGNATION: Executive Engineer