

FIELD INSPECTION REPORT

Date of Inspection : 24.12.2020		District: w. Champaran	
Division : RMD. Work. Div. Bagaha-1		Length (km): 6.30 km.	
Name of the Road: PWD Road to Soha.			
Scheme/Programme:		MAINTENANCE	
Package No.: RM	WE	BH 19/0008	Road Id No.: 318901031856
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance New maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	—	S
b)	Condition of Surfacing	—	S
c)	Riding Quality	—	S
d)	Road Camber	—	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	—	yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		yes
4.	Compliance History		
a)	Status of ATR's & any others	— NO.	

C-C pavement
not provided

Overall Rating :

Satisfactory (S)	—	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

21/12/2020
(Signature) 24.12.2020

NAME: Ratnesh Paswan
DESIGNATION: — Executive Engineer