

FIELD INSPECTION REPORT

| | | | |
|------------------------|--|--------------|--------------|
| Date of Inspection : | 24.12.2020 | District: | W. Champaran |
| Division : | RWD WORK: Division | Length (km): | 16.80km. |
| Name of the Road: | Bagaha - PWD Road Canal to Belaung | | |
| Scheme/Programme: | MAINTENANCE | | |
| Package No.: | RM/WE/BAG/19/0009 | Road Id No.: | 31809102031 |
| Status of the Project: | Ongoing/Completed/Under Maintenance | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance New. Maintaining. | | |

| Sl. No. | Parameters to be checked | Remarks |
|---------|--|---------|
| 1. | Pavement | |
| a) | Road Junction condition | S |
| b) | Condition of Surfacing | S |
| c) | Riding Quality | S |
| d) | Road Camber | S |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | |
| f) | Contraction Joints provided or not (CC Pavement) | |
| g) | Compaction of flank/slope & raincuts if any | yes |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | |
| c) | Condition of railings/slab/approach for Bridges | |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | yes |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | no |

C.C. Pavement
SRI provided

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME:

Ratnesk Paswan

(Signature)

DESIGNATION:

Executive Engineer

24-12-2020