New M/R

FIELD INSPECTION REPORT

Date O	f Inspection	18.12 WW		Bhotpur	100 <u>100 100</u>
Divisio	on - PIRU	ig	Length (km):	1.10 km	
Name	of the Road:	PWD Road to	Jasidih Road		-
	e/Programme	MAINTENANCE	المارين		-
Packag		V 191000 G	load Id No.: 10 46 1	601020	Co. Make
Status	of the Project :	Ongoing/Completeted/		/	
Work is a case of:		New Connectivity/Up gradation/Maintenance			
SI No.		Parameters to be checked	d	Remarks	
1	Pavment				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			¹\$/U	
c)	Riding Quality			vs/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No ?	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No_J	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage		Company of the second s	San San Stewart	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	N-
b)	Condition of railings/slab/approach for Bridges			S/SRI/U	
c)	Road Furniture				
3 a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No		
4	Compliance History			4.111.	/ = !
a)	Status of ATR's & any others			NIL	
				(6)	12
Overall Rating : Satisfa		Satisfactory (S)	(ann)	(3)	
		Satisfactory but require	es Improvement (SRI)		110
		Unsatisfactory (U)			

Name:

Desigination

Scanned with CamScanner