

(53)

old/MR

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020	District: Ara
Division : Ara	Length (km): 1.00 KM
Name of the Road: PWD Road to Gopipur	10401608147
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10401608147
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI)
Unsatisfactory (U)	

Remarks : Appearance of a few potholes & edge-breakage. 200m & km stones not found. Cautionary boards missing. Parapets not painted.

(Signature)

NAME:

Rectification done or not : Not
 Rectification started or not : Not
 Notice issued or not : Not

23/12/20
 EE
 (N.A. ISHRAAT)