

(67) Old M/R

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: Arun	
Division : N.A.		Length (km): 5.600 Km	
Name of the Road: NIT 30 Sakadole to Jambalpur		PO No: 1608153	
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S(U)
b)	Condition of Surfacing	S(U)
c)	Riding Quality	S(U)
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	(U)

Remarks: appearance of patches, pots & edge-breakage almost throughout the length of the road.
Less road furniture.

NAME:

Rectification made or not : Not
Rectification started or not : Not
Notice issued or not : Not

(Signature)

23/12/20

EE

(N.A. ISHRAT)