

56

ad M/R

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020	District: Ang
Division : Ang	Length (km): 10.2 km
Name of the Road: Caidha MOKhalise to Anam Pur	
Scheme/Programme: MAINTENANCE	to Khesarya Baga Nagluwan
Package No.:	Road Id/No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Remarks: Appearance of edge-breakage, dominant over, pots & patches; Exposed aggregates in CC pavement in some length. Road furniture deficiency is markable.

NAME:

Rectification done or not : Not
Rectification started or not : Not
Notice issued or not : Not

(Signature) 
23/12/20
EE
(N.A. ISHRAT)