

55

FIELD INSPECTION REPORT

Old M/R

Date of Inspection : 23-12-2020		District: Arq	
Division : A-29		Length (km): 2.75 km	
Name of the Road: Kulharya village to Kulharya station Road			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		S/U ✓
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓S/U
f)	Contraction Joints provided or not (CC Pavement)		Yes/No ✓
g)	Compaction of flank/slope & raincuts if any		Yes/No ✓
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges		S/SRI/U ✓
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained		200m Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Remarks: Exposed aggregates in CC pavement (not throughout)
 Appearance of edge-breakage, patches at some places.
 Road furniture is deficient.

NAME:

Rectification done or not: Not
 Rectification started or not: Not
 Notice issued or not: Not

(Signature)

23/12/20

EE

(N.A. ISHAKAT)