FIELD INSPECTION REPORT

Date of Inspection: 19.12. 20 00			District: Kou'mur	
Division: Mohania			Length (km): · 仏奴八八 ·	
Name of	the Road: K	hajuna to MAINTENANCE	Ramgarh	
Scheme/T	rogramme:	MAINTENANCE	0	
Package !			Road Id No.:	
			Completed/Under Maintenance	
Work is	a case of:		was man election	Remarks
SI No.		Parameters to	o be checked	Кстагка
1	Pavement		ration .	
n)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			, √s/u
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
: f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drains			si wasanii
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/\$RI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnit	_		en kara e Merie
a)	Whether sign stones/Paven	Yes/No		
2021 A	Compliance	History		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Mosmen (Signature)

NA

NAME: ARUN KUMAR MAHTO

Status of ATR's & any others

DESIGNATION: SE-cum SQC.

Scanned with CamScanner

Scanned with CamScanner