

FIELD INSPECTION REPORT

Date of Inspection:	20.12.2020	District:	Kaimur
Division:	Bhabua	Length (km):	2.3
Name of the Road:	Bhalehiyarkhan Raura to chainpers Road		
Scheme/Programme:	MAINTENANCE		
Package/No.:	Road Id No.: 10201400818		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sr. No.	Particulars to be checked	Rating	
1.	Pavement		
a)	Road function condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregate in case of CC Pavement	Yes/No	
f)	Contraction Joint provided or not (CC Pavement)	Yes/No	
g)	Composition of Bank/slope & reticent if any	Yes/No	
2.	Cross Drainage		
a)	Condition of headwater/abutment pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stone/Pavement road markings are provided and maintained	Yes/No	
4.	Other Items History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires improvement (SR)	
Unsatisfactory (U)	

20/12/2020
(Signature)

NAME: Er. Arun Kumar Mahato.

DESIGNATION: S.E.