FIELD INSPECTION REPORT

Date of Inspection: 19-12-2020			District: Kaimus	
Division: Mohania			Length (km): 1.100	
Name of	the Road: Ma	shaw a Chaus	a State Hishways to horge	ira River
Scheme	Programme:	MAINTENANCE	100 100 100 100 100 100 100 100 100 100	
Package No.:		1 1 1 1 1 1	Road Id No.: 10301500819	
			ed/Under Maintenance //Up gradation/ Maintenance	
Activity 12	a case of:	1	lo be checked	Remarks
SI No.		11.2	1.100	of the second control of the second
1	Pavement		Washington and the second	
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			-SIU
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
. ()	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			~Yes/No
2.	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.1	Rond Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
10 4 IV	Compliance History			
a)	Status of ATI	R's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	and the second second

Logo Sign is not available required resetting of Sign Board

(Signature) 12. 2000

NAME: ARUN KUMAR MAHTO

DESIGNATION: SE-cum SQC.

Scanned with CamScanner