

FIELD INSPECTION REPORT

Date of Inspection : 19-12-2020	District: Kaimur (Bhabua)	
Division : Bhabua	Length (km): 4.100	
Name of the Road: Bare Sonhan Road TO NH2 (Pusauli) via Rampur		
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.: 10301408006	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ^x
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

* Road Signes to be refixed and repainted.

Arunkumar Mahto
(Signature) 19.12.2020

NAME: Arunkumar Mahto

DESIGNATION: SE - cum S.O.C.