

FIELD INSPECTION REPORT

Date of Inspection : 20.12.2020 District: Kaimur
 Division : Bhabua Length (km): 5.42
 Name of the Road: Keshri chand Durganki Path (Chauri) - Dulhi
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: NEA 22000994
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S1
b)	Condition of Surfacing	S1
c)	Riding Quality	✓ S1
d)	Road Camber	✓ S1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI) ✓

Unsatisfactory (U)

work under progress. Road Furniture to be improved, installed, Road marking to be done.

Inspected
(Signature) 20.12.2020

NAME: Er. Arun Kumar Mahto.

S.E.