

### FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District : Bhagalpur	
Division : Kahalgaon		Length (km) : 6.7	
Name of Road : Gopali Chowk Aamgachha to Tiwari Tola via Hajurnagar Santhali Tola path			
Scheme/Programme : OLD MR			
Package No. :		Road Id No.: 20703400822	
Status of the Project : Under Maintenance			
Work is a case of : Maintenance			
SL No.	Parameters to be checked	Remarks	
<b>1</b>	<b>Pavement</b>		
a)	Road Junction condition	S	
b)	Condition of Surfacing	SRI	
c)	Riding Quality	SRI	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes	
f)	Contraction Joints provided or not (CC Pavement)	Yes	
g)	Compaction of flank/slope & raincuts if any	No	
<b>2</b>	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	SRI	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	
c)	Condition of railings/slab/approach for Bridges	NA	
<b>3</b>	<b>Road Furniture</b>		
a)	Whether <b>sign board</b> /informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes	
<b>4</b>	<b>Compliance History</b>		
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S)	<b>SRI</b>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : KUMAR RAKESH

(Signature)

DESIGNATION : EXECUTIVE ENGINEER

*[Signature]*  
21.12.2020