

FIELD INSPECTION REPORT

Date of Inspection : 22.12.2020		District : Bhagalpur
Division : Kahalgaon		Length (km) : 10.2
Name of Road : Jagadispur More Barahat PWD Path to Gauripur via Bhagaiya Path		
Scheme/Programme : OLD MR		
Package No. :		Road Id No.: 20703400824
Status of the Project : Under Maintenance		
Work is a case of : Maintenance		
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	RI
c)	Riding Quality	RI
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	No.
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3	Road Furniture	
a)	Whether sign board /informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	RI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

(Signature)

[Handwritten Signature]
21.12.2020