

FIELD INSPECTION REPORT

Date of Inspection : 22/12/20	District: Purnia
Division : R.W.D. D.J. Purnia	Length (km): 2.70 K.M
Name of the Road: Baniyopatti Chaur to Sobutter	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 2020 R-3
Status of the Project: Ongoing Completed Under Maintenance	
Work is a case of: New Connectivity Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	U/S
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	U

(Signature) 22/12/20

NAME: ABDUL SABBAR

DESIGNATION: A.E