FIELD INSPECTION REPORT

Date of	Inspection:- 23	-12-20 Dis	trict:- Sheohar.	CON
Divisio	n. RWD Works D	v Sheohar Lei	igth (km):- 1.30	KW
Name (of the Road:-	anaisbus to Ke	19WA TOLA	
Scheme	e/Programme:-	MAINTENANCE	TMOS	
Packag	e No .:- BABRA	\S9 Ro	nd Id No:	
Status	of the Project: O	ngoing/Completed/Ur	ider Maintenance	10000
Work i	ork is a case of: New Connectivity/Up gradation/ Mainte			Remarks
Sl. No.				Kemarks
1.	Pavement			√S/U
a)	Road Junction condition			S/UV
b)	Condition of Surfacing			
c)	Riding Quality			√S/U
d)	Road Camber			VS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No V
f)	Contraction Joints provided or not (CC Pavement)			/Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No~
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutments & Wing walls, Slab in RCC			S/SRI/U P/K
c)	Condition of railing/slab/approach for bridges			S/SRI/U N
3.	Road Furniture			
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained		Yes/No~	
4.	Compliance Hist			
a)	Status of ATR's & any others		NO	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Name: Dilly Karner

(Signature)

DESIGNATION: - Junios Engineex