## FIELD INSPECTION REPORT

	FIELD MOI BC			
f Inspection:	23/1420	District.		
Division: montal		Length (km): 2.622 K.M.		
of the Road:		itar toli	Ł	
Scheme/Programme: MAINTENANCE				
Package No.:				
Status of the Project: Ongoing/Completed/		Chigaretta	main termina	
			The Particular States	
Sl. No. Parameters to be checked Remarks				
Pavement			in a second second	
Road Junction condition			S/U	
			S/U	
			S/U	
			S/U	
Whether free from defects such as visible cracks, exposed			Yes/No	
Contraction Joints provided or not (CC Pavement)			Yes/No	
Compaction of flank/slope & raincuts if any			Yes/No	
Cross Drainag				
Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
			∽S/SRI/U	
Condition of railings/slab/approach for Bridges			S/SRI/U	
Road Furniture				
Whether sign b stones/Pavement	ooards/informatory/ca troad markings are p	autionary Board/km & 200m rovided and maintained	Yes/No	
Compliance His	fory -			
Status of ATR's	& any others		- NIA -	
	Programme: e No.: f the Project: a case of:  Pavement Road Junction Condition of So Riding Quality Road Camber Whether free aggregates in ca Contraction Joi Compaction of Cross Drainag Condition of he Condition of Ab Condition of Ab Condition of rai Road Furniture Whether sign between the compliance His	Inspection:  In:  In:  In:  In:  In:  In:  In:	Inspection: 23 1470 District: East champer of the Road: Longth (km): 2.622 K. Market to the Road: Longth (km): 2.622 K. Market to the Road: Maintenance Maintenance of the Project: Ongoing/Completed/Under Maintenance out of a case of: New Connectivity/Up gradation/ Maintenance  Parameters to be checked  Pavement  Road Junction condition  Condition of Surfacing  Riding Quality  Road Camber  Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Contraction Joints provided or not (CC Pavement)  Compaction of flank/slope & raincuts if any  Cross Drainage  Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts  Condition of railings/slab/approach for Bridges  Road Furniture  Whether sign boards/informatory/cautionary Board/km & 200m cones/Pavement road markings are provided and maintained	

Overall Rating :

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	- '

(Poly 23/12/20

(Signature)

NAME: Motoshhan Sharmar

**DESIGNATION:**  $\mathcal{T} \cdot \mathcal{E} \cdot$