


FIELD INSPECTION REPORT

| Date of Inspection : 12/12/2020 | | District: Samastipur | |
|---|--|--|--|
| Division : Samastipur | | Length (km): 0.770 km. | |
| Name of the Road: Mathurapur Ghat to Mahadalit Jola | | | |
| Scheme/Programme: | | MAINTENANCE MMGSY (Sc) | |
| Package No.: | | Road Id No.: 32010113037 | |
| Status of the Project: | | Ongoing/Completed/Under Maintenance | |
| Work is a case of: | | New Connectivity/Up gradation/ Maintenance | |
| SJ No. | Parameters to be checked | Remarks | |
| 1. | Pavement | | |
| a) | Road Junction condition | S/U | |
| b) | Condition of Surfacing | S/U | |
| c) | Riding Quality | S/U | |
| d) | Road Camber | S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | Nil | |

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | — |
| Unsatisfactory (U) | — |

NAME: Vivekanand


13/12/2020
(Signature) JE