FIELD INSPECTION REPORT

Date of Inspection : 20	4-12-2020	District: Somartipur	
Division: Some	Hirur	Length (km): 1.51	
Name of the Road: To	1 to Laguniya	Sway Kanth Yadar Mushas Tola.	
Scheme/Programme:	MAINTENANCE	, MMGSY (SC).	
Package No.:		Road Id No.: 32010113038	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity	/Up gradation/ Maintenance	

l No.	Parameters to be checked	Remarks
1.	Payement	Assert House
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Santat 24-12 2000

(Signature)

NAME: SANTOSH KR. THAKUR

JE, R.W.D.