

FIELD INSPECTION REPORT

Date of Inspection : 23/12/2020	District: Purnea	
Division : R.W.D.-Div Purnea	Length (km): 0.708K-5	
Name of the Road: LO 53 TO prapatti musahari (UR-65)		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	SU
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Munim Lal Das
(Signature)

NAME: MUNI LAL DAS

DESIGNATION: J.W.