

Block - piprahi

FIELD INSPECTION REPORT

Date of Inspection : - 18.12.2020	District: - Sheohar
Division : - R.W.D. Sheohar	Length (km): - 1.20 km
Name of the Road: Abdul Haq Maulana ke Ghar to Mallah Tola	
Scheme/Programme: MAINTENANCE (G.T.S.N.Y.)	Road Id No.:
Package No.:	Status of the Project: Ongoing/Completed/Under Maintenance ✓
Work is a case of: ✓	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No A.T.R. is pending in this scheme.

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Kumar
18.12.2020
(Signature)

NAME: - Sudhir Kumar

DESIGNATION: - A.E.