

FIELD INSPECTION REPORT

Date of Inspection:- 16.12.20		District:- Sheohar.	
Division:-RWD, Works Div. Sheohar		Length (km):- 1.20 KM	
Name of the Road:- Mahendra Mehta House Sugali to Dairy Farm Bhisamod Sugali (HTSNY)			
Scheme/Programme:-		MAINTENANCE	
Package No.:-		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank/slope & raincuts if any		✓Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U N/A
b)	Condition of Abutments & Wing walls, Slab in RCC culverts		S/SRI/U N/A
c)	Condition of railing/slab/approach for bridges		S/SRI/U N/A
3.	Road Furniture		
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained		✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Name:- Rajesh Kumar

(Signature)

DESIGNATION:- Junior Engineer