

FIELD INSPECTION REPORT

Date of Inspection :	17/12/2020	District:	Patna Champarn
Division :		Length (km):	
Name of the Road:	L028 to Hasua		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No AS
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S
g)	Compaction of flank/slope & raincuts if any	Yes/No <i>flank, raincut required.</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <i>S.R.I.</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <i>N.A.</i>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <i>N.A.</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <i>200m, sign Board / cautioning must required.</i>
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

SM
17/12/2020
(Signature)

NAME: *Sunil Kumar Singh*