


FIELD INSPECTION REPORT

Date of Inspection : 23/12/20		District: East Champaran
Division : Mithlata		Length (km): 2.250 K.M.
Name of the Road: Lora to Kaimaula		
Scheme/Programme: MAINTENANCE		PMGSY
Package No.: BAIR - 692		Road Id No.: -
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	- NIA -

Overall Rating :

Satisfactory (S)	✓S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


 23/12/20
 (Signature)

NAME: Makreshwar Sharma

DESIGNATION: J.E.