FIELD INSPECTION REPORT

Divisi	of Inspection:	191142	District: East chamfara Length (km):	m
	of the Road: N		10. 4.	
	ne/Programme:	MAINTENANC	E / CITSALY	- Thyrad
	ge No.:	_	Road Id No.:	(
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters	to be checked	Remarks
1.	Pavement			
a)	Road Junction condition			~S/U
b)	Condition of Surfacing			-37Ú
c)	Riding Quality			√S/Ū
d)	Road Camber			-S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage			C. C. N
a)	Condition of head walls in Hume pipe culverts including its painting			S/SŘI/U
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts			~S/SRI/U
/	Condition of railings/slab/approach for Bridges			\\$/\SRI/U
	Road Furniture			
) s	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
. (ompliance His	ory		Anna Prima
The state of the s	Status of ATR's &			-NIA

Overall Rating

	*
Satisfactory (S)	(\$),
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	_
Chomores (-)	

(Signature)

NAME:

mallshwar sharmes

DESIGNATION:

T.F.