

FIELD INSPECTION REPORT

Date of Inspection : 20/12/2020	District: Banka
Division : Banka - I	Length (km): 0.450 km
Name of the Road: Khasuri Chhatrahar Road to Bari Khasuri	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/C
b)	Condition of Surfacing	✓ S/C
c)	Riding Quality	✓ S/C
d)	Road Camber	✓ S/C
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U N/A
c)	Condition of railings/slab/approach for Bridges	S SRI U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Kumar Jaiswal
(Signature) 20/12/20