## FIELD INSPECTION REPORT

Date of	Inspection:	20/12/20	District: East Chamfan	40-1
Division: montari			Length (km): 1.70 Kim	~~ <u>~</u>
Name o				Supri Ma
	Programme:	MAINTENANCE	/ GISNY SOR	
Package No.:			Road Id No.:	, ř.
Status of the Project: Ongoing/Completed				
The state of the s			p gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			the soft and the comme
a)	Road Junction condition			S/Ú ·
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/Ú
d)	Road Camber			SPÚ
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			¥es/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	e and		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S∕SRI/U
c) ,	Condition of railings/slab/approach for Bridges			√S/SRI/U
3.	Road Furnitur			
a)			autionary Board/km & 200m rovided and maintained	Yes/No
4.	Compliance Hi	story		paring Solver to
a)	Status of ATR's	& any others		-NIA -

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SAI
Unsatisfactory (U)	_

(Signature)

NAME:

moleshwar sharma

DESIGNATION:

7.6