

FIELD INSPECTION REPORT

Date of Inspection : 22/12/2020		District: Purnea
Division : R.W.D. Div - Purnea		Length (km): 1672
Name of the Road: Barniyapatti Nahar to Nayspatti		
Scheme/Programme: MAINTENANCE		Road Id No.:
Package No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	USA
a)	Road Junction condition	✓
b)	Condition of Surfacing	USA
c)	Riding Quality	USA
d)	Road Camber	USA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature) 22/12/20

NAME: ABDUL JABBAR

DESIGNATION: A.E