

FIELD INSPECTION REPORT

Date of Inspection : 24/12/20	District: Nalanda
Division : Rajgir	Length (km): 2.065 K.m.
Name of the Road: Ratna Pakki Sadak To Kharjamma Path To Shesh Bhag Tak Path	
Scheme Programme: MAINTENANCE	NABARD
Package No.:	Road Id No.:
Status of the Project: Ongoing Completed Under Maintenance	
Work is a case of: New Connectivity Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S
c)	Riding Quality	S/U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/✓
g)	Compaction of flank/slope & raincuts if any	Yes/✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (N/A)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (N/A)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ramprakash Kumar
JE

NAME: Rajgir

24/12/20
(Signature)