## FIELD INSPECTION REPORT

Date	of Inspection:	17/12/20	District: Gast chamfo	van
Divisi	ion: Motific	stri	Length (km): 2.345 K	
Name	of the Road:	Toy-to math T	ola	7
Scheme/Programme:		MAINTENANCE / HMGJY (SC)		
Package No.:		Road Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			unit
a)	Road Junction	condition		√S/U
b)	Condition of Su	urfacing		\S/U
c)	Riding Quality			~S/U
d)	Road Camber			√8/ÍU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			¥es/No
f)	Contraction Joints provided or not (CC Pavement)			¥es/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			The second second
a)	Condition of head walls in Hume pipe culverts including its painting			∿S/SRI/U
) (	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
(	Condition of railings/slab/approach for Bridges			S/SRI/U
İ	Road Furniture			
y st	Whether sign bottones/Pavement r	oards/informatory/cau road markings are pro	tionary Board/km & 200m vided and maintained	Yes/No
C	ompliance Hist	)ry		griffer ( to to the first of th
St	tatus of ATR's &	any others		- A/A -

Overall Rating

Satisfactory (S)	`\$'
Satisfactory but requires Improvement (SRI)	•
Unsatisfactory (U)	- 1

(Signature)

NAME: Make Sharme, Sharme,

DESIGNATION: 2.E.