FIELD INSPECTION REPORT MMUSY (SC)

Date of I	nspection: 24	-12-2020	District: Sempertia		7
District: Somartipus Division: Somartipus Name of the Road: TO) to Marlan Mushari Scheme/Programme: MAINTENANCE MAINTENANCE			1		
vame of	the Road: To	1 to Marks	my MI. al		
Charles and Charles	8	MAINTENANCE,	MMGSY (SC)		
Package Status of	110.:		Road Id No.: 32 010101	326.	7
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.	a case of.	THE PROPERTY OF THE PROPERTY OF	Particular and Control of the Contro	Lacasea	1
		Parameters to	be checked	Remarks	
1.	Pavement .				
a)	Road Junction condition			S/U	5
b)	Condition of Surfacing			S/U	S
c)	Riding Quality			S/U	5
d)	Road Camber			S/U	5
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	Ye
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any			Yes/No	5/4
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	不
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	14
c)	Condition of railings/slab/approach for Bridges .			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	4.0
4.	Compliance History				
a)	Status of ATR's & any others				MA

Overall Rating

Satisfactory (S)	_5-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: SANTOSH KR. THAKUR

(Signature)