

FIELD INSPECTION REPORT

Date of Inspection :	02/12/20	District:	Banka
Division :	Banka	Length (km):	4.640
Name of the Road:	Shombhugari Assargari path to Birnaulke road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/ ☒ Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ ☒ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU S
b)	Condition of Surfacing	SU S
c)	Riding Quality	SU S
d)	Road Carriber	SU S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SSRI S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SSRI NA
c)	Condition of railings/slab/approach for Bridges	SSRI NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No S
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Satisfactory

Pritam
02/12/2020
(Signature)

NAME: