

# FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020		District: PURNEA	
Division : PURNEA		Length (km): 1.645	
Name of the Road: REPAIR of ROAD FROM KAMALFOR NURSE SCHOOL to beyond more southward			
Scheme/Programme: MAINTENANCE			
Package No.: —		Road Id No.: 21105200839	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
<b>1. Pavement</b>			
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	S/U ✓	
c)	Riding Quality	S/U ✓	
d)	Road Camber	S/U ✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
<b>2. Cross Drainage</b>			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U ✓	
c)	Condition of railings/slab/approach for Bridges	S/SR/U ✓	
<b>3. Road Furniture</b>			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
<b>4. Compliance History</b>			
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	✓ (U)

NAME:

SANTAY KUMAR SINHA

S.E. PURNEA

(Signature) 11-11-20

(SANTAY K. SINHA)