## FIELD INSPECTION REPORT

Date of Inspection: 23.12.2020		District : Bhagalpur	
Division	n : Bhagalpur	Length (km): 2.25	
Name o	of Road : Nonsar Manjhi Tola Chowk to Rampu	r via Navin Tola	-
Scheme	e/Programme : New Maintenance Policy 2018	· · · · · · · · · · · · · · · · · · ·	-
Package No.: 11 Road Id No.: 27321033245			
Status	of the Project : Ongoing		
Work is	s a case of : Upgradation		
SI. No.	Parameters to be checked		Remarks
1	Pavement		
a)	Road Junction condition		NA
b)	Condition of Surfacing		NA
c)	Riding Quality		NA
d)	Road Camber		NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		No.
f)	Contraction Joints provided or not (CC Pavement)		Yes
g)	Compaction of flank/slope & raincuts if any		NA
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NA
c)	Condition of railings/slab/approach for Bridges		NA
3	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained		No
_4_	Compliance History		
a)	Status of ATR's & any others : Culvert under Construction		No.

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	RI
Unsatisfactory (U)	

(Signature)

NAME: KUMAR RAKESH

**DESIGNATION: EXECUTIVE ENGINEER**