

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 1.5
Name of Road : Asarganj RCD Road to Deodha		
Scheme/Programme : OLD MR		
Package No. :		Road Id No.: 20703200838
Status of the Project : Under Maintenance		
Work is a case of : Maintenance		
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	No.
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes
4	Compliance History	
a)	Status of ATR's & any others :	

Overall Rating :

Satisfactory (S)	U
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

(Signature)

[Signature]
23.12.2020