## FIELD INSPECTION REPORT

-	Inspection :	25/12/2020	District:	P.	etng		
Division : Name of the Road:		Masayshi	Length (km):	0.	4501	okm	
The order of the second	STORESTON OF THE PARTY OF THE P	SOLT TO C	sala par				
Package	/Programme:	IMAINTENANCE	Road Id No.:			4-1	
The second second second	f the Project:	Ongoing/Complete	d/Under Maintenance	~			
	n case of:		Up gradation/ Mainten				
SI. No.		Parameters to	o be checked		1	Remarks	
1.	Pavement						
a)	Road Junction condition					s s/U	
b)	Condition of Surfacing				9	s s/u	
c)	Riding Quality				2	S/U	
d)	Road Camber				3	S/U	
e)	Whether free from defects such as visible cracks, exposaggregates in case of CC Pavement.					Ho Yes/No	
f)	Contraction Joints provided or not (CC Pavement)				- Yes/No		
g)	Compaction of flank/slope & raincuts if any				- Yes/No		
2.	Cross Deair						
a)	Condition of head walls in Hume pipe culverts including its pain				nting HA S/SRI/U		
ь)	Condition of Abutment & Wing walls, Slab in RCC culverts				HA S/SRI/U		
c)	Condition of railings/slab/approach for Bridges				HAS/SRI/U		
3.	Road Furni	Control of the Contro					
a)	Whether sig	n boards/informato ment road markings	ory/cautionary Board, are provided and main	km & ntained	200m	Yes/No	
4.	Compliance	History					
a)		R's & any others					

Overall Rating

Satisfactory (S)	CTIT
Satisfactory but requires Improvement (\$RI)	SKL
Unsatisfactory (U)	

(Signature)

Dinesh choodhary

NAME: