

FIELD INSPECTION REPORT


Date of Inspection: - 24.12.20		District: - Kishanganj
Division: - Kishanganj-1		Length(km): 2.597 K.M
Name of the Road: - LOTS - LO4570 Bochagharzi (VR75)		
Scheme/Programme: PMGSY		
Package No.: BR-18R-086		Road Id No.: 21205802095
Status of the Project:		Ongoing/Completed /Under Maintenance
Work is a case of:		New Connectivity/ Up gradation / Maintenance
S1. No	<u>Parameters to be checked</u>	
1.	Pavement	Remarks
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank / slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory(S)	- S -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

Remarks - Road, Chainage 1.500 to END is badly effected during last year flood. due to this road is damaged up above part of the road.

NAME: E. Radheshyam prajapati
J.E, R.W.D, Bahadurganj-1


J.E 24.12.20
R.W.D (W) Division
Kishanganj-1