

FIELD INSPECTION REPORT

Date of Inspection : 20.12.2020	District: Kishanganj
Division : Kishanganj-2	Length (km): 2.427
Name of the Road: Thakurgaon Kharudah Road to Baddi Bhitra (New Urban)	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 212059/3011
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U — S
b)	Condition of Surfacing	S/U — S
c)	Riding Quality	S/U — S
d)	Road Camber	S/U — S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U — S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U — S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U — U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

[Signature]
2012-2020
(Signature)