


**FIELD INSPECTION REPORT**

|                                                                   |  |                                                            |  |
|-------------------------------------------------------------------|--|------------------------------------------------------------|--|
| Date of Inspection : 24/12/20                                     |  | District: Araria                                           |  |
| Division : Forbesganj                                             |  | Length (km):                                               |  |
| Name of the Road: Kothi Kapur South Khutaha to Chauva Adiwasi Tor |  |                                                            |  |
| Scheme/Programme: MAINTENANCE                                     |  | Road Id No.:                                               |  |
| Package No.:                                                      |  | Status of the Project: Ongoing/Completed/Under Maintenance |  |
| Work is a case of:                                                |  | New Connectivity/Up gradation/ Maintenance                 |  |

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | Pavement                                                                                                             | S/U ✓     |
| a)      | Road Junction condition                                                                                              | S/U ✓     |
| b)      | Condition of Surfacing                                                                                               | S/U ✓     |
| c)      | Riding Quality                                                                                                       | S/U ✓     |
| d)      | Road Camber                                                                                                          |           |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No    |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No    |
| 2.      | Cross Drainage                                                                                                       |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U ✓ |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U ✓ |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U   |
| 3.      | Road Furniture                                                                                                       |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓  |
| 4.      | Compliance History                                                                                                   |           |
| a)      | Status of ATR's & any others                                                                                         |           |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          | U |

  
 Cupre  
 24/12/20  
 (Signature)

NAME: