FIELD INSPECTION REPORT

Date	of Inspection :	24/12/020	District: Chapra			
	sion: ch	apra-1	Length (km): 1.0 law			
	e of the Road: H	along Karbnista	n Main good to Garleha ch	hirand man		
1	Scheme/Programme: MAINTENANCE MM(15) (Ger)					
	age No.:		Road Id No.:			
_	s of the Project:	Ongoing/Completed/Under Maintenance				
THE WAY THE PARTY	Work is a case of: New Connectivity/Up gradation/ Maintenance					
-	Sl. No. Parameters to be checked					
1.	Pavement			in a second		
a)	Road Junction condition			S/U		
b)	Condition of Surfacing			S/U-		
c)	Riding Quality			S/U		
d)	Road Camber			S/U		
e)	Whether free aggregates in ca	Yes/No				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No		
g)	Compaction of flank/slope & raincuts if any			Yes/No		
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U		
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U		
c)	Condition of railings/slab/approach for Bridges			S/SRI/U		
3.	Road Furniture			esta de la como de la		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No			
4.	Compliance His	lory				
a)	Status of ATR's	& any others				

Overall Rating :

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U

NAME:

DESIGNATION: