

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: Gopalganj
Division : Hathua		Length (km): 1.758 km
Name of the Road: Hathua-Kusaudi Road to Rajputola (W.B)		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/N S
b)	Condition of Surfacing	S/N S
c)	Riding Quality	S/N S
d)	Road Camber	S/N S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

(Signature) 23/12/20

NAME: M.S. Siddiqui

DESIGNATION: 