

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020	District: Muzaffarpur
Division : Muzaffarpur East-1	Length (km): 2.09 KM
Name of the Road: Baliya Balaur Path Ke Vishwan Ashan to Khatigarpur Mohan Ray Tol	
Scheme/Programme: MAINTENANCE	MMGSY (SS)
Package No.:	Road Id No.: 315072-13011
Status of the Project: Ongoing Completed Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Some 200M post missing Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	
✓ Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

Bijendra Kumar
17-12-2020

DESIGNATION:

JE / RWD (W)
Kurhani

K. Dinesh
17/12/2020
(Signature)
AE
RWD (W)
Kurhani