

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020	District: Muzaffarpur
Division : Muzaffarpur East-1	Length (km): 2.805 KM
Name of the Road: Kobiya Sahpur Pnqsy Jagdamba Asthan to Balaurdih	
Scheme/Programme: MAINTENANCE MNGSY (6e)	
Package No.:	Road Id No.: 31504213013
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New/Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Flume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board-km & 200m stones/Pavement road markings are provided and maintained	Some 200m post missing Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N-A

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	U

Road surface damaged due to heavy rain and flood.

NAME: Bijendra Kumar
 DESIGNATION: JE / RWD (W)
 Kurnani

K. Anshu
 17/12/20
 (Signature)

AE
 RWD (W)
 Kurnani