

FIELD INSPECTION REPORT

Date of Inspection : 10/12/20		District: East Champaran
Division : Mithari		Length (km): 1.145 Km
Name of the Road: Kobeyra To Jhangardali		
Scheme/Programme: MAINTENANCE		MUSY
Package No.: —		Road Id No.: —
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRU/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRU/U
c)	Condition of railings/slab/approach for Bridges	S/SRU/U NA
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4. Compliance History		
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory (U)	

NAME: Rajendra P. Yadav
DESIGNATION: A.E

10/12/20
S.E

(Signature)
12/12/20