

Date of Inspection : 24.12.20		Length (km):	East chambers
Division : Morarj		to Chitaha	
Name of the Road: Mishra in tola		Road Id No.:	
Scheme/Programme: MAINTENANCE		Ongoing/Completed/Under Maintenance	
Package No.:		New Connectivity/Up gradation/ Maintenance	
Status of the Project:		Parameters to be checked	
Work is a case of:		Remarks	
Sl. No.			
1.	Pavement	S/U	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	Yes/No	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture	Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History	No	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

24/12/20
(Signature)

NAME: Manish Kumar
DESIGNATION: J-E-R-W-D-Morarij