

FIELD INSPECTION REPORT

Date of Inspection : 20/12/20
 Division : Forest
 Name of the Road : Lakshmi
 Scheme/Programme : MAINTENANCE
 Package No. :
 Status of the Project : Ongoing/Completed/Under Maintenance
 Work is a case of : New Connectivity/Up gradation/ Maintenance

Parameters to be checked

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	OK
b)	Condition of Surfacing	OK
c)	Riding Quality	OK
d)	Road Camber	OK
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	OK
f)	Contraction Joints provided or not (CC Pavement)	OK
g)	Compaction of flank/slope & raincut (if any)	OK
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S
b)	Condition of Abutment & Wing walls, Slab in R.C.C. culverts	S/S
c)	Condition of railings/slab/approach for Bridges	S/S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	OK
4.	Compliance History	
a)	Status of ATR's & any others	OK

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: Manish Kumar

DESIGNATION: J.E. R.W.D. Arora